

DCN No. E010525-01

<u>California Institute of Technology</u> Massachusetts Institute of Technology

Document Ch	(DCN)	Sheet 1	of 2		
DOCUMENT No. (DOC-REV-GP.ID)	TITLE				NEW REV
D990694-B (PCB)	LSC Whitening Filter Rev B PCB Modification			B1	
CHANGE DESCRIPTION (FROM/TO):					
The poorly routed trace is removed from the circuit and replaced with jumper wires. Via removal is accomplished by hand using a 40 mil drill bit. Do not drill through board as internal planes may be shorted or internal traces may be cut. 1. Remove (top layer only) via pad under the "2" in "U20" silkscreen. 2. Remove (top layer only) via pad on first "9" of "R99" silkscreen. 3. Place wire from pad of R100 to pad of C167 (pads across from U20 pin 8). 4. Place wire from pad of R99 (pad closest to U20) to pads connected in step 3. See figure on page two. REASON FOR CHANGE:Severe cross coupling to channel 5 caused by poorly routed traces on the board.					
Schematically the board is correct, but the connections were poorly routed. ACTION: Incorporate Change Attach DCN to Drawings Other Action (specify):					
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS) DCN DISTRIBUTE					N
No hardware was affected (record change only): Barish Coles					Coyne
List S/Ns which comply already: Lazzarini Lindquist Shoemaker Stapfer				Lindquist Stapfer	Sanders Tyler
List S/Ns to be reworked/scrapped: Weiss Whitcomb				Matherny	
List S/N's to be built with this change: Raab McCarthy R. Abbott R. Abbott					Wooley
List S/Ns to be retested per this change:					
Modify all boards as operations permit					
SAFETY, COST, SCHEDULE,	REQUIREMENTS IMPAC	T? NO YES (If	YES, enter CR (C	CB) or TCP (TR	B) #)
APPROVALS	S: DATE OTHER APPROVALS (SPECIFY)			DATE	
ORIGINATOR:	12/21/01				
TASK LEADER:					
GROUP LEADER:					
DCC RELEASE:					

