

Input Optics Installation


- Introduction to IO System
- Installation Progress and Status
- Problems and Solutions
- Upcoming

SCANNED



Input Optics System

Pre-Stabilized Laser <> IO <> Interferometer



Input Optics System (cont'd)

- Laser beam steering and conditioning
 - » Beam waist size and position
 - » Wave front distortion and losses
 - » Polarization
 - » Beam pickoffs and for diagnostic
 - » Safety concerns
- RF phase modulation
 - » Three modulation frequencies
 - resonant side bands
 - non-resonant side bands
 - mode cleaner
 - » Alignment
 - » Thermal effect
 - » RFAM



Input Optics System (cont'd)

- Mode-Cleaner

- » Suspended 15m triangular cavity
 - Finesse = 1550, FSR ~ 10 MHz
- » Rejection of the higher order modes
- » Improve laser frequency stability
- » Suppression of intensity noise and beam wiggle

- Mode-matching Telescope


- » Three-element design with suspended mirrors
 - independent adjustment of waist size and position
 - beam steering into IFO

- Faraday Isolator and IFO Signal Extraction

- » In-Vacuum components
- » Thermal lensing and wave front distortion
- » depolarization and Isolation




PSL/IO Table Layout




PSL/IO Table Layout (cont'd)

- Modulation Optics




PSL/IO Table Layout (cont'd)

- MC Mode Matching Telescope




PSL/IO Table Layout (cont'd)


- Periscope, MC Beam Actuators, OSA




IO_overviewR.jpg




1-25-99 Single pass isolation




2-22-99 29.5 MHz EOM sensitivity




2-25-99 PSL profile around MC waist




In Vacuum Layout - HAM 7,8




HAM 7 Layout






HAM 8 Layout



WILLIAMS

P0000432.jpg



Magnet Bonding Problems

- Bonding failures at various stages of the suspended optics installation
- One single failure delays the installation about a week on an average
- 112 glue joints in IO system (SOS) and the same number of joints in COC (LOS)
- Throughput <50%



Possible Causes of the Bonding Problems



- Contamination
 - >> Gloves
 - >> Bonding/sanding fixture
 - >> Glue applicator
 - >> Silicone
 - >> ...
- Thermal effects
 - >> Vacuum baking (80 C)
 - >> Post-bake cleaning (70 C)
- Chemical effects
 - >> Cleaning solution
 - >> DI water
- Epoxy (VacSeal) Degradation
- Process control ...




Bonding Investigation

- Tiger team
- Tests
 - » cure Epoxy at elevated temperature
 - » Indium bonding
 - » Silicate bonding







Bonding Strength Tests for Epoxy Joints cured at 100° C

- Test setup
- Test magnet-Al standoff joint and Al standoff-glass joint at various stages of the suspension preparation process
 - » after cure at 100°C for 2 hours
 - » before and after vacuum bake
 - » before and after cleaning process
- Results
 - » Both M-Al and Al-G joints are stronger than 3 kg before cleaning.
 - » Vacuum bake does not affect the strength at 3 kg level
 - » cleaning process weakens the bond. After cleaning,
 - M-Al joints break at 1.3-2.8 kg
 - 2 out of 9 Al-G joints break at 2.8 kg



New Procedure (Solution)


- Eliminating all the contamination sources we can think of
- New Epoxy (VacSeal)
- Cure Epoxy at elevated temperature (100°C)
 - » New gluing fixtures have been made
- New cleaning procedure
 - » reduced soaking time
 - » optical contamination tests



sanding.jpg



MirrorCure.jpg



Upcoming

- Finish three SOSs (MCCM, MCFM, MMT2)
 - » 2 weeks
- In-vacuum installation
 - » 1 week
- Finalize non-vacuum opto-mechanical parts installation
 - » depending on progress of RFAM measurements (ISC/IO)
- MC alignment
 - » 1-2 weeks
- Lock MC in air at low laser power (ISC/IO)

