



HAM2-H1



Luke's Layout

Most of the Laser Beams are pretty much on target (on X & Y Axis) except for the following components:


- 1- SM2: $X = -559.5$; $Y = 630.9$; $Z = 100$; $Yaw = 143.531^\circ$
- 2- PRM: $X = -69.9$; $Y = -628.0$; $Z = -96.8$; $Yaw = 179.574^\circ$
3. Missing Component ID and Coord's. Laser Beam path is Different from Actual layout
4. Laser Beam path is lower than in actual layout.




Actual Layout

(Includes the latest Laser Beam File D0901920-v4)

HAM8-H2



Luke's Layout



Actual Layout

(Includes Laser Beam file d0902345-v2)

1, 2 & 3 are missing components in actual layout.
I need ID and coords.

4 & 5 look out of position on actual layout. Maybe with latest
Zemax file, they are OK