

1. ALL DIMENSIONS ARE IN INCHES
2. REMOVE ALL BURRS AND BREAK SHARP
EDGES TO A MINIMUM OF 0, 015 IN
3. ALL MACHINING TO BE PERFORMED
AFTER WELDING IS COMPLETED 4. THOROUGHLY CLEAN TO REMOVE ALL DIL, GREASE, DIRT & CHIPS
5. APPLY PRIMER AND PAINT (BLACK) TO ALL VISIBLE SURFACES

ALL DIMENSIONS ARE IN INCHES TOLERANCES: X, XX: +/- 0, 03"

X. XI +/- 0.1"

D010227-B-D LIGO PROJECT L JONES 5/21/02

OVERHEAD BSC CROSSBEAM BRACKET