DOCUMENT No. (DOC-REV-GP.ID)	TLE
D030168-A LOS Coil Whitening Board	rd
CHANGE DESCRIPTION (FROM/TO): Rev A is the intial release of the board. The pcb is but Rev A1 cuts the ground connection on pin 2 of U29 at the property of U29 at the U29 at the property of U29 at the U29	

NEW REV

**A**1

REASON FOR CHANGE:Change is needed to make the fault logic function properly.						
ACTION:						
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)  DCN DISTRIBUTION				N		
☐ No hardware was affected (record change only):			Barish	Coles	Coyne	
Lief S/Ne which comply already:			Lindquist Stapfer	Sanders Tyler		
☐ List S/Ns to be reworked/scrapped: All boards will be produced w/ change. Weiss Whitcon				Whitcomb	Matherny	
List S/N's to be built with this change:					Wooley	
☐ List S/Ns to be retested per this change:						
SAFETY, COST, SCHEDULE, REQUIREMEN	TS IMPACT	T? NO YES (II	YES, enter CR (C	CB) or TCP (TR	(B) #)	
APPROVALS:	DATE	OTHER APPROVALS (SI	PECIFY)		DATE	
ORIGINATOR:	5/15/03					
TASK LEADER:						
GROUP LEADER:						
DCC RELEASE:						