



Version History:
Version 1 - Initial Release
Version 2 - S2, the Head Transimpedance Switch was mounted backwards on the PCB. Pinout of 25 pin connector serving the DCPD was wrong on V1. Blown fuse LEDs were labeled backwards. V2 fixes these errors.

