
+15V
-15V
Hi Voltage Mon.
To ADC
Hi Voltage Drive
From DAC
Alt. Drive
Input
WARNING
HIGH VOLTAGE
+15V
-15V
Hi Voltage Mon.
To ADC
Hi Voltage Drive
From DAC
Alt. Drive
Input
Alt. Dither
Input
+15V
-15V
Low Voltage Drive
From DAC
Shutter Trigger
Input
Trigger
Low Voltage Mon.
To ADC
OMC Piezo Driver
D1300485