

DCN No.	E010158-00-C					
SHEET	1	OF	1			

DOCUME								
DOCUMENT No. (DOC-REV-GP. ID)	TITLE						NEW REV.	
D980013-B-C	LOS Suspension				С			
	1		10					
CHANGE DESCRIPTION (FROM/TO): 1. Compensation networks added to coil drivers.								
	2. Char	nged coil driver	: 183 ohm resistors (R	202, R21	16, R229,	R243,	ı	
R256) to 125 ohm, 2 watt,								
,			dd14 added to board to		ze and lim	it higt	n frea	
gain of 1Hz zero, 40Hz pol		_	dar radica to oodia t	5 5 td 51112	ze una mi	iit iiigi	rmeq	
gam or file zero, Toriz por	*	Q	ld20 added to coil driv	er for or	amn inn	ut pr of	· A.C	
tion.	4. Dau	ar unough Dac	id20 added to con driv	CI 101 0 ₁	amp mp	ut prot		
tion.								
REASON FOR CHANGE: Field	changes made to	increase reliabi	lity and performance.					
ACTION: Incorporate change	Attach DCN to dr	awing(s) Othe	r action (specify):					
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS) DCN DISTRIBUTIO								
No hardware affected (record change only) Althouse Barish Co						Coles		
List S/Ns which comply already: Coyne Lazzarini Linc Lucas Sanders Shoo							uist aker	
List S/Ns to be reworked or scrapped: Stapfer Tyler Vogt								
List S/Ns to be built with this change: Weiss Whitcomb Your								
List S/Ns to be retested per this change: McCarthy								
SAFETY, COST, SCHEDULE, REQU	JIREMENTS IMPACT?	No Y	es (If yes, enter CR (CCB) or T	CP (TRB) n	10.)	
APPROVALS:		DATE	OTHER APPROVAL	LS (specify)		DAT	E	
ORIGINATOR: J. Heefner		8/23/01						
TASK LEADER: R. Bork								
GROUP LEADER:								
DCC RELEASE:								