



## DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D980013-C	LOS Suspension Controller	D

**CHANGE DESCRIPTION (FROM/TO):** Added resistors Radd6, Radd7, Radd8, Radd9 to terminate unused inputs of MAX333 switches on boards.

**REASON FOR CHANGE:** Improper termination can cause excess noise in the circuit.

**ACTION:**  Incorporate change     Attach DCN to drawing(s)     Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)	DCN DISTRIBUTION
<input type="checkbox"/> No hardware affected (record change only)	Althouse    Barish    Coles
<input type="checkbox"/> List S/Ns which comply already:	Coyne        Lazzarini    Lindquist
<input type="checkbox"/> List S/Ns to be reworked or scrapped:	Lucas        Sanders       Shoemaker
<input type="checkbox"/> List S/Ns to be built with this change:	Stapfer      Tyler         Vogt
<input type="checkbox"/> List S/Ns to be retested per this change:	Weiss        Whitcomb    Young
<input checked="" type="checkbox"/> All boards should be upgraded as operations permit.	McCarthy
<input type="checkbox"/>	Wooley
<input type="checkbox"/>	
<input type="checkbox"/>	

**SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT?**     No     Yes (If yes, enter CR (CCB) or TCP (TRB) no. )

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
<b>ORIGINATOR:</b> J. Heefner	10/3/01		
<b>TASK LEADER:</b>			
<b>GROUP LEADER:</b> D. Coyne			
<b>DCC RELEASE:</b>			