1	111	11	U)	
2	47	4	-	
-	Ы	G		,
	/			

DCN No. E020013-00

<u>California Institute of Technology</u> Massachusetts Institute of Technology

Document Change Notice (DCN) Sheet 1 of 1						
DOCUMENT No. (DOC-REV-GP.ID)	TITLE					
D980323-B	Mode Cleaner Steering Mirror Driver				С	
CHANGE DESCRIPTION	at connector J7 with jum at connectors with SMB ctors.		selection.			
REASON FOR CHANG	GE:Front panel connec	tor required for 40 m	eter configuratio	on.		
ACTION: X Incor	porate Change 🗌 Attac	ch DCN to Drawings	Other Action (s)	pecify):		
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS) DCN DISTRIBUT				N DISTRIBUTION	1	
No hardware was affected (record change only): Barish Coles					Coyne	
List S/Ns which compl	Ns which comply already: Lazzarini Lindquist Shoemaker Stapfer				Sanders Tyler	
List S/Ns to be reworked/scrapped: Weiss Whitcomb					Matherny Wooley	
List S/N's to be built with this change: Raab McCarthy   B. Abbott B. Abbott					wooley	
List S/Ns to be retested per this change:						
All new modules will be	e produced as rev C.					
SAFETY, COST, SCHEDULE,	REQUIREMENTS IMPACT	? <b>NO YES</b> (	(If YES, enter CR (CO	CB) or TCP (TR	<b>B</b> ) #)	
APPROVALS	PROVALS: DATE OTHER APPROVALS (SPECIFY)					
ORIGINATOR:	1/10/02					
TASK LEADER:						
GROUP LEADER:					Ī	
DCC RELEASE:						