



Document Change Notice (DCN) Title: DCN HEPI Actuator Assembly

Document No. Doc-Rev	Title HEPI Actuator Assembly	New Rev
D020284-B	HEPI Hydraulic Actuator General View	C
D020357-A	Actuator Exploded Assembly	B
D020358-A	Actuator Plate Exploded Assembly	B
D080344-00	HEPI Actuator Bleed Tube Assembly	A
D080345-00	HEPI Actuator Bleed Tube Insert Sleeve	A

CHANGE DESCRIPTION (FROM/TO) – Continue on next sheet if needed:

D020284-C Updated to As-Built Configuration
 D020357-B Updated to As-Built Configuration
 D020358-B Updated to As-Built Configuration

D080344-A Initial Release
 D080345-A Initial Release

REASON FOR CHANGE: Updating actuator drawings to changes made during the assembly at LLO. D080344 and D080345 are replacing two drawings that matched drawing numbers existing in the DCC,

ACTION: Incorporate Change Attach DCN to Drawings Other Action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)	DCN DISTRIBUTION
<input type="checkbox"/> List S/Ns to be retested per this change: None <input type="checkbox"/> Other disposition/instructions or additional comments: None	Required: excomm (Lab Grp Leads, LSC Spokesperson) Michael Landry (LHO AdL Liaison) Brian O'Reilly (LLO AdL Liaison) Bill Tyler (Lab Safety & QA)
	Recommended (AdL Area/Subsys Leads & Cog. Sci./Eng., subsystem email distribution lists): <i>[please delete if/as appropriate for this DCN]</i>
	Additional Distribution List for this DCN:

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? NO YES
 (If YES, enter CR (CCB) or TCP (TRB) #)

--	--	--



APPROVALS:	DATE	OTHER APPROVALS (SPECIFY)	DATE
ORIGINATOR:			
TASK LEADER:			
GROUP LEADER:			
DCC RELEASE:			

(Continue on sheet 2 if needed)

<input checked="" type="checkbox"/> No hardware was affected (record change only):
<input type="checkbox"/> List S/Ns which comply already:
<input type="checkbox"/> List S/Ns to be reworked/scrapped:
<input checked="" type="checkbox"/> List S/N's to be built with this change: all