

L190-E980559-00-D

FROM : Panasonic FAX SYSTEM

PHONE NO. :

Dec. 08 1998 12:00PM P1

INITIATOR WKW
DATE 11/19/98

ENGINEERING CHANGE REQUEST (ECR)

NEXT ASSEMBLY NO. _____

CUSTOMER DRAWING NO. D972211-F

DRAWING TITLE 1150 BSC DOWNTUBE WELDMENT

REVISION: FROM F TO H



HYTEC
INCORPORATED

DESCRIPTION OF CHANGE (Simple Phrase, Identify Dimensions If Possible):

ON SHIT 4 (D4) CHANGE ϕ .250 I.O.D. THRU TO
 ϕ .261 \pm .010.

REASONS FOR CHANGE:

.250 \pm .0002 PIN IN BRACKET ASSY D972398
DOES NOT FIT.

IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):

INTERFACE	RESPONSIBLE PARTY	INITIAL

NOTIFY COGNIZANT DESIGNER: R. SMITH

NOTIFY COGNIZANT ENGINEER: T. THOMPSON

APPROVED: [Signature]

Submitted 12/9/98
Bev