

DATE 8/10/98

LI90-E980596-00-D

**ENGINEERING CHANGE REQUEST (ECR)**

NEXT ASSEMBLY NO. 972501

CUSTOMER DRAWING NO. 972710

DRAWING TITLE #AM Optical Table

REVISION: FROM E TO F



**HYTEC**  
INCORPORATED

**DESCRIPTION OF CHANGE (Simple Please. Identify Dimensions if Possible):**

- Missing 10-32 holes needed for wire tie-downs. Add holes similar to what was on original d/wa on support table.

- Please Note 10-32 UNC is really UNF =>

**REASONS FOR CHANGE:**

- Req'd for assembly

**IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):**

INTERFACE	RESPONSIBLE PARTY	INITIAL

NOTIFY COGNIZANT DESIGNER: Roan

NOTIFY COGNIZANT ENGINEER: Tnn

APPROVED: [Signature]