PHYSICS MONITORING SYSTEM WBS 1.2.3

Rainer Weiss March 20, 1996 (Derived from original Sept 20, 1994) LIGO-G960048-00-M

PHYSICS MONITORING SYSTEM WBS 1.2.3

Cost:

Design			cost	% cont.	cont.	total
Fab		\$	338K	5%	\$ 17K	\$ 355K
TOTAL	WA LA	\$	1642K 1114K	5% 5%	\$ 82K 56K	\$ 1724K 1169K
TOTAL		2	3093K	5%	\$ 155K	\$ 3248K

Function:

Measure time and amplitude of disturbances in the physical environment of the interferometers.

- Veto in burst detection to reduce non-Gaussian noise
- Correlation in periodic and stochastic source detection
- Determine sensitivity to environment for interferometer development
- Provide diagnostic information on interferometer and facility performance
- Measure or set limits on correlation of environmental noise at separated sites

Instruments and requirements:

Seismic noise			
3 axis seismometer	10^{-10} m	@ 1Hz	1/bldg
2 axis tiltmeter	10^{-9} rad	@ 1Hz	1/bldg
1 axis accelerometer	10^{-11} m	@ 100Hz	9/tank
1 axis accelerometer	10^{-11} m	@ 100Hz	12/tube module
Acoustic noise			, and a module
Electret microphone	10^{-8} atm	@ 100Hz	1/tank
Magnetic fields			W. Constitution of State
3 axis magnetometer	10^{-4} gauss	@ 100Hz	1/tank
Radio Interference			
Multichannel receiver	$3\mu \mathrm{volt/cm}$	6 chan	1/bldg
Cosmic ray muons			
Scintillation detector	$10^{-2} \ \mu/{\rm sec \ cm^2}$	$\leq 100~{ m Mev}$	1/bldg
Power line fluct.	10-3		
Line monitor	10^{-3}	$\geq 10^{-3} \mathrm{sec}$	1/bldg
Residual gas	< 10-14 .		40.00
Residual gas analyser Residual gas analyser	≤ 10 11 torr	1 - 300 amu	
Contamination	≤ 10 forr	1 - 300 amu	2/tube module
Crystal monitor head	monologram/l-		9 12 3
RGA head	$\leq 10^{-14} \text{ torr}$	1 200	1/tank
Control	7 10 toll	1 - 300 amu	
04			1/bldg

DESIGN (1997)

WBS: 1.2.3.1

Personnel

scientist	12 man months
engineer	9
technician	6

Tasks:

- Final definition of system requirements
- Define system interface to CDS
- \bullet Define test program and software algorithm development
- System documentation
- Test of contamination monitor

FABRICATION (1998)

WBS: 1.2.3.2, 1.2.3.3

Personnel

scientist	2 man months
engineer	4
technician	6

Tasks:

- Instrument procurement
- \bullet Fabricate specialized fixtures for facility installation
- Test some of the instruments (Q&A)
- Develop operating software and documentation
- \bullet Design facility installation schedule and test program