

G960150-

G960150-01-0-P

1

1 . Southwest Arm at station 44+00 looking west at 60" RCP Culverts.

G960150- 02-0-P


² .Southwest Arm at station 67+00 looking west at electricalPowerline being raised.





G960150-03-0-P

³ Southwest arm at station 130+00 looking west at disking of intermediate lift of fill on end station.



G960150-04 -O-P

4. Southwest Arm at Station 130+00 looking north at excavating and spreading fill at end station.

G960150-05-0-P

5 .Southeast Arm at Station 27+00 looking south at wet fill being plowed for drying.





G960150-06-0-P

6 .Southeast Arm at station 34+00 looking south at berm fill being compacted with sheepsfoot roller.

2



G960150-07-O-P

7. Southeast arm at Station 47+00 looking southeast at fill being excavated, placed and spread on berm.

G960150-08-0-P

8. Southeast Arm at Station 74+00 looking North at berm fill being disked to reduce moisture content before compaction.





G960150-09-0-P

9. Southeast arm at station 74+00 lookingSE, at wet fill being plowed to hasten drying.



G960150- 10-0-P

10. Southeast arm at station128+00 looking SW at spreading and compacting fill near end station

G960150-11 -O-P

11. Southeast Arm at station 130+00 looking south at excavating and hauling fill for end station.





G960150-12 -0-P

12. Southeast Arm at station 130+00 looking west at excavating fill for placement on end station.

4