DATE DCN# DRAWING TREE # NOTES CONTINUED: (5) SCRIBE, ENGRAVE (A VIBRATORY TOOL MAY BE USED), LASER MARK OR MECHANICALLY STAMP (NO INKS OR DYES) DRAWING PART NUMBER, 1 JUN 2011 (NO INKS OR DYES) DRAWING PART NUMBER, REVISION (AND VARIANT OR "TYPE" IF APPLICABLE) ON NOTED SURFACE OF PART FOLLOWED ON THE NEXT LINE WITH A THREE DIGIT SERIAL NUMBER. SERIAL NUMBERS START AT 001 FOR THE FIRST ARTICLE AND PROCEED CONSECUTIVELY. USE MINIMUM 0.12" HIGH CHARACTERS, UNLESS THE SIZE OF THE PART DICTATES SMALLER CHARACTERS. EXAMPLE: DXXXXXXXX-VY, TYPE-XX, S/N XXX 6. APPROXIMATE WEIGHT = 0.83 LB. 7. MACHINE ALL SURFACES TO REMOVE OXIDES AND MILL FINISH, USE OF ABRASIVE REMOVAL TECHNIQUES IS NOT ALLOWED. REFER TO LIGO-E0900364 8. ALL PARTS SHALL BE MANUFACTURED IN ACCORDANCE WITH LIGO SPECIFICATION E0900364. 9. ALL MATERIAL IS TO BE VIRGIN MATERIAL (i.e. NO WELD REPAIRS, PLUGS OR RECYCLED MATERIAL). NO REPAIRS SHALL BE MADE UNLESS APPROVED IN ADVANCE, AND IN WRITING, BY LIGO LABORATORY. REFER TO LIGO-E0900364. - \emptyset 48 RAISED BOSS ┌ 2X 8.13 32.5 20.5 2X 45° → 2X 23 **~** → 2X 20 **~** \ 2X 10 X 45° 1 X 45° NOTES AND TOLERANCES: (UNLESS OTHERWISE SPECIFIED) PART NAME CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY 1. INTERPRET DRAWING PER ASME Y14.5-1994.
2. REMOVE ALL SHARP EDGES, .005-.015. FOR MACHINED PARTS. ROUND ALL EDGES APPROXIMATLEY R.02 FOR SHEET METAL PARTS.
3. DO NOT SCALE FROM DRAWING. QUAD LIFTING BAR CLAMP DIMENSIONS ARE IN MILLIMETERS SYSTEM TOLERANCES: .XX ± .25 .XXX ± .13 SUB-SYSTEM DESIGNERK. BUCKLAND1 JUN 2011SIZEDWG. NO. 4. ALL MACHINING FLUIDS MUST BE FULLY SYNTHETIC, FULLY WATER SOLUBLE AND FREE OF SULFUR, SILICONE, AND CHLORINE. ADVANCED LIGO SUS DRAFTER K. BUCKLAND 1 JUN 2011 **NEXT ASSY** CHECKER ANGULAR ± .5° 6061-T6 Al 63 µinch APPROVAL SCALE: 1:1 PROJECTION: