				DCN No. E000022-00-C		
		STITUTE OF TECHNOLOGY	r DGY	SHEET	<u>1</u> OF	1
DOCUME						
DOCUMENT No.	NT CHANG	ENUTICE				NEW
(DOC-REV-GP. ID)			TITLE			REV.
D990155-A-C	Generic DAQ Int	erface Module				В
			·····			
			1 11110 / 11		14	
CHANGE DESCRIPTION (FROM/T		and the second s	1 and U12 to allo			
+/- 15 VDC bus power onl ified.	ly. Exisiting rev A	and rev 00 board	s are compatible a	s is and do	not need	to be mod-
				······································		
······································						
1.1.1007,11.2.1.1.101 - 1.1.1.1.0 (0.10000000000000000000000000						
		········· ······				-
			·····			
				·····		
		1977 - 111 - 111 - 11				
REASON FOR CHANGE: Regul	lators III and III2	Were unnecessar	$\frac{1}{15}$ $\frac{1}{15}$	available i	n all CDS	eurocard
crates		were unnecessar	y us +-15 VDC 15	avanable		ourocura
ACTION: Incorporate change	e Attach DCN to	drawing(s) 🔀 Ot	her action (specify):	New bo	ards are n	nanufac-
tured under Rev B. Exisiti		수는 것이가 가슴을 알았다. 승규는 것이 가지?				
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)				DCN DISTRIBUTION		
No hardware affected (record change only)				Covne	Barish Lazzarini	Coles Lindquist
List S/Ns which comply already:					Sanders	Shoemaker
List S/Ns to be reworked or scrapped:				Stapfer Weiss	Tyler Whitcomb	
List S/Ns to be built with this change:						
List S/Ns to be retested per this change:				McCarth Bork	ıy	
				DOIK		
		· · · · · · · · · · · · · · · · · · ·				
SAFETY, COST, SCHEDULE, REQ	UIREMENTS IMPACT?		If yes, enter CR (CCB)	or TCP (TRB)	no.)
APPROVALS		DATE	OTHER APPROV			DATE
	1-1	1/31/00				·······
TASK LEADER:	Inh.	2/7/00				
DCC RELEASE:	MIL	£.7.00				