

<u>California Institute of Technology</u> Massachusetts Institute of Technology

DCN No. E010206-00-C

Document Change Notice (DCN) Sheet 1 of 1				
DOCUMENT No. (DOC-REV-GP,ID)	TITLE			NEW REV
D010001-A-C	SOS Coil Driver Module		A1	
2. Changed R12, R9, R voltage monitors for ch	29, R43, R55 from 523, 1 34, R32, R46 to 1K and a annel 0.5V/V.	l/2 watt to 511, 1/2 watt. added Radd1, Radd2, Rad		
ACTION: Inc	orporate Change Atta	ch DCN to Drawings	Other Action (specify):	
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS) DCN DISTRIBUTIO				TON
No hardware was affected (record change only): Barish Coles Lazzarini Lindquist				Coyne
List S/Ns which comply already: Shoemaker Stapfer				Tyler
List S/Ns to be reworked/scrapped: Weiss Whitcomb Raab				b Matherny
List S/N's to be built with this change: McCarthy				
List S/Ns to be retested per this change: Wooley				
Upgrade all field mod	dules as operations permit			
SAFETY, COST, SCHEDUL	E, REQUIREMENTS IMPAC	$\Gamma? \qquad \boxed{\qquad NO \qquad \boxed{\qquad YES (If}}$	YES, enter CR (CCB) or TCP ((TRB) #)
APPROVA	LS: DATE OTHER APPROVALS (SPECIFY)			DATE
ORIGINATOR: Heefner 10/18/01				
TASK LEADER:				
GROUP LEADER:				
DCC RELEASE:				