

DCN No. E040053-00-E

<u>California Institute of Technology</u> Massachusetts Institute of Technology

Document Change Notice (DCN)				Sheet 1	of 1	
DOCUMENT No. (DOC-REV-GP.ID)	TITLE HEPI Side & Back Foundation Plate Mounting Hole Reloactions					NEW REV
E040011-A	d Installation Procedu	stallation Procedure			В	
CHANGE DESCRIPTI	ON (FROM/TO):					
E040049 - Housing L REASON FOR CHANC	BSC Lifting Proced ocation Procedure.	n Procedure: Has beer ure, E040050 – HAM cedures for lifting of	Lifting	Procedure and	d E040043 –	BSC Pier –
housing on top of the BS	•					
ACTION: Incor	porate Change 🛛 🗌 A	Attach DCN to Drawings		Other Action (s	pecify):	
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)				DCN DISTRIBUTION		
No hardware was affected (record change only):				Barish Lazzarini Shoemaker	Coles Lindquist Stapfer	Coyne Sanders
L I ist S/Ns which comply already.						Sanders Tyler
List S/Ns to be reworked/scrapped: Weiss Whitcomb Raab						Matherny
List S/N's to be built with this change:						
List S/Ns to be retested per this change:						
SAFETY, COST, SCHEDULE,	REQUIREMENTS IMPA		YES (If Y	ES, enter CR (C	CB) or TCP (TR	(B) #)
APPROVALS	S: DATE OTHER APPROVALS (SPECIFY)					DATE
ORIGINATOR: O. Spjeld	d 03/02/0	04				
TASK LEADER: Ken Ma	ason					
GROUP LEADER: Ken	Mason					
DCC RELEASE:						