## advancedligo

DCC Number: E 070282-00-D

Date Prepared: 11-08-07

Originator	Cognizant Engineer	Ext./Phone#	Project	Account Number
Rodica Martin	Rodica Martin	352-392-3776	ELIGO IO	
			OPTICS	
			CALTECH	
			BAKE REO	
			MIRRORS 1	

Dwg/Part Number	Rev	Part Description / Material	Serial Number	Qty
E070162-00		REO ELIGO MIRROR#1, 45 DEG AOI, LOT# I0EOU, RUN#S4-743 / FUSED SILICA	16, 18, 22, 24	4
		REO ELIGO MIRROR#1, 45 DEG AOI, LOT# I0EG1, RUN#S4-742 / FUSED SILICA	02, 03	2

Used In (next higher assembly): ELIGO IO FARADAY ISOLATOR

Vendor Name PO/Contract Number

REO 1636-000001139

Data Package, Receiving/Inspection Remarks:

Inspection Required Y/N	Visual Damage Y/N	Comments	Name/ Initials	Date Comp.
N				

## **Process Flow:**

#	Operation	<b>Start Date</b>	Work Area	Instructions	Name/	Date Comp.
					<b>Initials</b>	
1	Clean			Per E000007-00, Class A		
2	Vacuum Bake			Per E960022-B, Class A, 120C for 48 hours		
3	Control Point			Review/Approve RGA scan		

N.B.: A copy of this traveller must be submitted to the DCC each time the original is shipped with the associated part(s) and when the traveller has been completed.

advancedlig	0

DCC Number: E 070282-00-D

Date Prepared: 11-08-07

#	Operation	Start Date	Work Area	Instructions	Name/	Date Comp.
"	Operation	Start Date	WOIR MICE	moti actions	Initials	Date Comp.
4	Wrap & Tag vacuum clean			Wrap each optic in lint free lens tissue, then twice in UHV		
	parts			foil and place in ameristat bag. Put this bag in a second		
				ameristat bag. Place bag in padded strong carboard box,		
				tight enough that it does not rattle inside and FedEx to LLO.		
5	Ship and Deliver/File			Please send to:		
	paperwork					
				Kate Dooley		
				LIGO Livingston Laboratory		
				19100 LIGO Lane		
				Livingston, LA 70754		
				Store all parts in the IO section of the clean LLO optics lab.		
				File one copy of traveler with the DCC.		
				Note: Ship original traveler with these parts.		
EN	D: Go to Traveler or procedure	associated wi	th next higher	r assembly processing		

## Special Instructions (Handling/Packaging Constraints, Remarks, etc.) or Notes:

PLEASE ADD SHIPPING INSURANCE FOR \$7,686.00, FABRICATION COST OF 6 MIRRORS.

N.B.: A copy of this traveller must be submitted to the DCC each time the original is shipped with the associated part(s) and when the traveller has been completed.