ECN NO. : $\underline{D972381-A}$

INITIATOR :_W.K. MILLER

DATE: <u>3/19/98</u>

ENGINEERING CHANGE NOTICE (ECN)

□ PDF SENT

LOCATION:

NEXT ASSEMBLY NO.: 972 CUSTOMER DRAWING NO.: D972381 DRAWING TITLE: BSC CENTERING JIG RIGHT SIDE ASSEMBLY ASSEMBLY					
			REVIS	ION: FROM0TOA	CORPORATED
			<u>ITEM</u>	DESCRIPTION OF CHANGE	
				(FROMTO) (ADD	
1	(DELETE				
2	CHANGED .50 REF. TO .50				
3	REPLACED ITEM 1 (D972422-1) WITH D972377-2				
4	REPLACED ITEM 3 (D972382-1) WITH (D972377-2)				
5					
6					
7					
8					
9					
<u>TITLE</u>	<u>SIGNATURE</u>	DATE APPROVED			
CHANG	ED BY: W.K. MILLER	3/4/98			
CHECK	ED BY:				
ENGINE	CER:				
APPROV	VED: TIM THOMPSON				
□ PDF	CREATED LOCATION:				