

INITIATOR BW

DATE 9-3-98

W190-E980579-00-D

**ENGINEERING CHANGE REQUEST (ECR)**

NEXT ASSEMBLY NO. \_\_\_\_\_

CUSTOMER DRAWING NO. D973001

DRAWING TITLE BSC TOP ASSY

REVISION: FROM 0 TO A



**HYTEC**  
INCORPORATED

**DESCRIPTION OF CHANGE (Simple Phrase, Identify Draw If Possible):**

IN P/L, ITEM 29: DELETE MDC PIN  
& CHANGE LENGTH TO 1.50  
ITEM 28: DELETE MDC PIN

**REASONS FOR CHANGE:**

1. 1.75" LONG BOLT IS TOO LONG
2. REDUCE COST BY USING STANDARD BOLTS

**IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):**

INTERFACE	RESPONSIBLE PARTY	INITIAL

NOTIFY COGNIZANT DESIGNER: ROGER

NOTIFY COGNIZANT ENGINEER: ERIC P

APPROVED: Tua