

Loading of GS-13 Flexure B after Vibratory Finishing at Max. Offset to Failure

