


Feedthrough documented here: **D1800038: D5-1D1 Flange**
Accuglass 25D-5CX2-450 Part # 100522
 See **FRS 9869 - Fix leak in HAM6 D5 Feedthrough**


Typical In-vacuum RFPD ASC (Wavefront Sensor) Wiring Chain

U7
In-vac ASC RFPD



To RF I/O Demodulator Patch Panels



To RF I/O Demodulator Patch Panels




Vacuum Side

Vacuum Feedthrough

Air Side



To ASC RFPD Interface D1101865



Version 1 - Initial Release
 Version 2 - Revised pinout to reflect the nonsensical way the single row coaxial 5-way D-sub was pinned in another conflicting, but older document.
 Version 3 - Added not so it's easy to tell which side to look at for the connectors.
 Version 4 - Updated for switch to Accuglass single row 5-way connector