Third IFO Component Loan Log

E1500229

06/17/2016 today's date

\$471,823.00 total implicit escrow total

Request	status	start	end	extention	loan value	released?	fol <u>low-up</u>	returned	form completion	escrow value	comments
E1500227	approved		07/01/2015		\$7,813.00		12/20/2016				1/26/16 Component request combined with E1500399. 4/28/2015 quote from Physik
					. ,					. ,	Instrumente: gty 1 S-330.4SD Piezo Tip/Tilt Platform, 5mrad (10 mrad Optical), Closed-
											Loop, Sub-D Delivery is ~ 4 weeks ARO . PSL-PZT Actuator . 03/15/16 - Per Rick S. At CIT.
											Should be ready for return. 04/25/16 - Spoke to Rick. He is going to check on the return.
E1500231	approved	04/27/2015	09/01/2015	08/01/2016	\$170,000.00	yes	07/01/2016	no		\$170,000.00	1/26/16 Waiting for LLO to complete the installation then will have to have the boards from
											LLO modified before returning to 3rd IFO. The primary delay was commissioning not allowing
											installation of components at LLO. Return date should be changed to 8/1/16.
<u>E1500298</u>	approved	07/16/2015	01/01/2016	01/01/2017	\$16,000.00	yes	12/01/2016	no		\$16,000.00	1/26/16 - The two busted PMC's are still being investigated and then still need to be
											reworked and rebuilt and then sent to LLO before the 3rd IFO one is released. I have no time
											frame on this work and it could quite easily be another year until this is complete. 03/15/16 -
											The two 3IFO PMCs. One at LLO as hot spare. One in LHO Lab being worked on.
E1500399	approved	10/01/2015	01/01/2016	01/01/2017	\$18,000.00	yes	12/01/2016	no		\$18,000.00	1/26/16 Staff only just identified (Alena Ananyeva) to work this. Work not started. Estimated
											work will start Feb 2016 and last 9 months. Return date should be changed to 1/1/2017
E1500430	approved	11/02/2015	11/01/2016		\$40,000.00	yes	10/01/2016	no		\$40,000.00	OFI Assembly - Shipped eLIGO weldment to LLO. This was not a 3IFO part. 01/29/16 - Gerardo
											shipped the internal parts for the OFI (from 3IFO inventory) on ICS shipment load #7973.
E1600026	a new second	01/20/2010	07/01/2016		\$10,000.00		06/01/2016			¢10.000.00	View Ports - Shipped 01/28/16, Shipment load # 7969
E1600026 E1600034	approved approved		05/01/2016		\$10,000.00		06/01/2016				Ring Heater Cables - Shipped to LLO, ICS shipment load #7982.
E1600090	approved	03/25/2016			\$2,000.00	yes ves	09/25/2016		requires signature		DCC #D1101005 S/N 20 - 6" HQ 0.75deg VP Optic. 04/25/16 - Shipped to LLO on ICS shipment
<u>L1000090</u>	approved	03/23/2010	2010			yes	05/25/2010	110	requires signature	Ş0.00	load #8102.
<u>E1600138</u>	approved	05/06/2016	08/01/2016		\$12,500.00	ves	07/01/2016	no		\$12,500.00	5 PSL HPO Laser Crystals - Peter K. shipped to LLO. Due to be replaced when LLO receives
		,,	,,		+,	,				+,	rplacement crystals in 08/2016. 05/25/16 - Peter K. & Jeff B. Searched the 3IFO and spare
											inventory accounted for a full set of laser crystals. (9 total 4 for the laser and 5 are spares). It
											was agreeded these 5 crystals came out of LHO spares and not 3IFO.
E1500003	approved	03/14/2016	2016		\$6,000.00	yes	09/14/2016	no	required	\$6,000.00	DCC # 9722012, 7.8" Viewport S/N 001. Released to Gerardo per E-Mail, with paperwork to
						-					follow. Verifyed with Joe DeRenzis this view port did come from the 3IFO inventory. Follow
											up paperwork will be required.
Prior to F1500003	approved	2015	2016		\$49,500.00	ves	09/01/2016	no		\$49.500.00	14 OpLev lasers. 4 - (HAM2-5) at Mid-X. 9 - Jason has for testing and will return when ready
					,	,		-			for storage. 1 - is owed to 3IFO, Jason will supply the LHO spares. 06/17/2016 Value based on
											old cost of \$5500.00/each. Trying to get current price.
Prior to F1500003	approved	2015	2016		\$117,000.00	yes	09/01/2016	no		\$117,000.00	ASC RFPD (x4), LSC RFPD (x2), DCPD for OMC (x2), Fast Shutter for ISC, Rich Abbott.
											Checked out and stored at CIT.
Prior to E1500003	approved	2015	2016	1	\$12,000.00	yes	09/01/2016	no		\$12,000.00	SEI Chasis checked out by Ops. These are in test stands and in lab being modified for
											Hardware watchdog work.
E1500447	approved	03/01/2016			\$22,000.00	HOLD				\$0.00	The Tiptilts are borrowed from spares inventory, NOT 3IFO inventory. There is a request for
											cables from 3IFO inventory not listed on this form. 01/28/2016 Checking with Dennis for
											approval of change.
E1500462	approved	02/01/2016	after 02		\$2,500.00	HOLD				\$0.00	1/26/16 pending with Jeff. 04/25/16 - Spoke with Jenne, AA chassis will be needed soon.
E1500460	approved	02/01/2016	after 02		\$55,000.00	0				\$11,010.00	1/26/16 pending with Jeff. 04/25/16 - Spoke with Jenne, Geophones will be needed soon.
						relased as					06/14/2016 Gave 6 L4Cs to David M. S/Ns are L41432, L414334, L41426, L41444, L41423,
						needed					L414443. The remaining L4Cs will be given out as they are needed. Valuing the L4Cs at
											\$1835.00 each.
E1500461	approved	02/01/2016	after 02		\$15,050.00	HOLD				\$0.00	1/26/16 pending with Jeff. 04/25/16 - Spoke with Jenne, IO chassis may not be needed.
			L	ļ				ļ			
E1600002		01/16/2016	07/06/2016			HOLD				\$0.00	PSL/IO Periscope. On hold. May not be needed.

<u>E1600025</u>	approved/returned				No			01/28/2016 We cannot supply the parts being requested. Only two sets of the Walking plates and the Platform A-D were manufactured for each site. There are no spares. Sent note to
								Dennis & Janeen.
E1500472	approved/re	turned			No			We think that there are copious spares. If no spares exsist (after careful search) then a loan
								from 3rd IFO stock is approved with the stipulation that the unit must be returned. 01/28/16
								note to Betsy to clairify cable request. 04/25/16 - These cables did NOT come from 3IFO
								stocks.
E1500317	rejected				No			
E1600072	closed	03/01/2016	03/21/2016		yes	yes	\$0.00	This loan can be closed. 03/29/2016 Returned the 3 SLEDs to TCS Box 10. S/Ns for the 840-5
								are 12.02.45, 12.02.47, for the 790-5 are 11.10.52, 11.10.39

follow-up - red date indicates scheduled follow-up, black date indidicates follow-up attempt