

J///// SYS Incoming Inspection Form

LIGO	F1800	0001-v1 S App	ert 13-Feb-18	
	Inspector	Regina Lee		Date 3/6/2018
P/N D1003301		Туре	v 9	S/N 002
Visual Inspection Comments: Possible machine marks along the back sides of baffle Front sides are very well polished no scratches or streaks seen				
Dimensional Inspection Comments:				
Nonconformities?	Y	4		

Description: